

Annual Waste Report: Yenda Waste Management Centre - 6263

Reporting Period: 2020 - 2021

Due: 29 August 2021

Status: **Certified**

Report Version: 1

Printed on: 9/9/2021, 12:03 PM

Printed by: John Roser, Certifier



No waste has been received, processed or removed from site during this period

Waste Received

Non-levied area

Municipal

	Waste type	Quantity (tonnes)
Received	Ferrous (iron or steel)	5.76
	Mixed waste	329.25
	Vegetation or garden	2.52
	<i>Total Municipal</i>	337.53

Commercial and Industrial

	Waste type	Quantity (tonnes)
	<i>Total Commercial and Industrial</i>	0.00

Construction and Demolition

	Waste type	Quantity (tonnes)
	<i>Total Construction and Demolition</i>	0.00

Unknown

	Waste type	Quantity (tonnes)
	<i>Total Unknown</i>	0.00

Annual Waste Report: Yenda Waste Management Centre - 6263

Reporting Period: 2020 - 2021
 Status: **Certified**
 Printed on: 9/9/2021, 12:03 PM

Due: 29 August 2021
 Report Version: 1
 Printed by: John Roser, Certifier



Deduction - Waste Transported from Site

Waste transported from site for disposal at a licensed waste facility

Waste type	Quantity
Waste Transported	
Bricks or concrete	6.72
Estimate of waste stream at time of receipt	<input type="checkbox"/> Unknown MUN: 100.00% C&I: 0.00% C&D: 0.00%
Ferrous (iron or steel)	131.72
Estimate of waste stream at time of receipt	<input type="checkbox"/> Unknown MUN: 100.00% C&I: 0.00% C&D: 0.00%
Mattresses	1.80
Estimate of waste stream at time of receipt	<input type="checkbox"/> Unknown MUN: 100.00% C&I: 0.00% C&D: 0.00%
Mixed waste	141.62
Estimate of waste stream at time of receipt	<input type="checkbox"/> Unknown MUN: 100.00% C&I: 0.00% C&D: 0.00%
Tyres	3.28
Estimate of waste stream at time of receipt	<input type="checkbox"/> Unknown MUN: 100.00% C&I: 0.00% C&D: 0.00%
Vegetation or garden	99.90
Estimate of waste stream at time of receipt	<input type="checkbox"/> Unknown MUN: 100.00% C&I: 0.00% C&D: 0.00%
Total	385.04

Waste transported from site under a Resource Recovery Order

Waste type	Quantity
Total	0.00

Waste transported from site for lawful recovery

Waste type	Quantity
Total	0.00

Annual Waste Report: Yenda Waste Management Centre - 6263

Reporting Period: 2020 - 2021
Status: **Certified**
Printed on: 9/9/2021, 12:03 PM

Due: 29 August 2021
Report Version: 1
Printed by: John Roser, Certifier



Summary Details

Details

	Tonnes
Waste Received - Waste received - Non-levied area	337.53
Waste transported from site	385.04 ^{less}
Net position for reporting preiod	-47.51

Certification Statement

I John Roser certify that the information contained in the report in respect of waste facility Yenda Waste Management Centre located at McManus Rd, Yenda, 2681 for the reporting period 2020 - 2021 is true and correct.

I further certify that the occupier of the waste facility has kept the necessary records to substantiate the information provided in this report in accordance with the Protection of the Environment Operations (Waste) Regulation 2014.

Please select the option that applies to you:

I am a person delegated to sign on the occupier's behalf and approved by the EPA in writing to sign this report